Weathertzenton Assistance Program

Work Order (Bid Form)

WORK ORDER INFORMATION

Work Order Name: WO/18018UE-1839/1

Work Order Type: Weatherization Audit Name: 18018UE-1839

CLIENT INFORMATION

Client Name: Address:

Client ID: 18018UE-1839

Alt. Client ID: Sullivan

<u>AGENCY INFORMATION</u>

Agency: Upper East Tennessee Human Development Agency Agency Phone: 246-6180

Address: 301 Louis Street Fax:

Company Name & License Number:	
Contractor's Signature:	

COMMENT

Vinyl siding and shingle roof 16' x 80'=1280 sq.ft. Has heat pump to heat and cool home has double pane windows some window need to rehab to make easy to open. Client in wheelchair (stated windows are hard toopen during time.)

Measures

	Measure 1 General Air Sealing			Components					Inspected
Comment				Estimated					
#	Material / Labor	Description / Comment	Units	Qty	Estimated Unit Cost	Total	Qty	Actual Unit Cost	Total
1		Rehab All windows	Each	10	Omit Oost	rotar	Q (y		Total
•	Miscella lieous ou	(hard to open and close)	Lacii	10					
1	Insulation	General air sealing (setup cost)	Each	10					
2	Labor	rehab door jamb	Each	1					
2	Construction Mate	Replace rotten wood at base of back door	Each	1					
	Other Detail								
L									
				Measur	e Sub Total:		,	Sub Total:	
	Measure 2 Ligh	ting [Kitche][3]			Componen	ts LT1		,	Inspected
	_	ting [Kitche][3]			Componen Estimated			Actual	Inspected
C	_	ting [Kitche][3] Description / Comment	Units	Qty	-		Qty		Inspected Total
C	Comment Material / Labor		<i>Units</i> Each	Qty 3	Estimated	1	Qty	Actual	
#	Comment Material / Labor	Description / Comment			Estimated	1	Qty	Actual	
# 1	Comment Material / Labor Labor	Description / Comment Compact Fl13 Watt	Each	3	Estimated	1	Qty	Actual	
# 1	Material / Labor Labor Lighting	Description / Comment Compact Fl13 Watt	Each	3	Estimated	1	Qty	Actual	
# 1	Material / Labor Labor Lighting	Description / Comment Compact Fl13 Watt	Each	3	Estimated	1	Qty	Actual	
# 1	Material / Labor Labor Lighting	Description / Comment Compact Fl13 Watt	Each Each	3	Estimated	1		Actual	

Report Run On: 4/2/2012

_	hting [Dining][4]			Componen	ts LT2			Inspecte
Comment			Estimated		Actual			
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Labor	Compact Fl13 Watt	Each	4					
1 Lighting	Compact Fl13 Watt	Each	4					
Other Detail								
] []	Cost To Cata	
			Measur	e Sub Total:		,	Sub Total:	
Measure 4 Lig	hting [Bedroo][2]			Componen	ts LT3		,	Inspecte
_	hting [Bedroo][2]			Componen Estimated			Actual	Inspecte
Comment	hting [Bedroo][2] Description / Comment	Units	Qty			Qty		Inspecte
Comment # Material / Labor		<i>Units</i> Each		Estimated		Qty	Actual	
Comment # Material / Labor 1 Labor	Description / Comment		Qty	Estimated		Qty	Actual	
Comment # Material / Labor 1 Labor	Description / Comment Compact Fl13 Watt	Each	Qty 2	Estimated		Qty	Actual	
# Material / Labor 1 Labor 1 Lighting	Description / Comment Compact Fl13 Watt	Each	Qty 2	Estimated		Qty	Actual	
# Material / Labor 1 Labor 1 Lighting	Description / Comment Compact Fl13 Watt	Each	Qty 2 2	Estimated Unit Cost			Actual Unit Cost	
# Material / Labor 1 Labor 1 Lighting Other Detail	Description / Comment Compact Fl13 Watt	Each	Qty 2 2	Estimated			Actual	
# Material / Labor 1 Labor 1 Lighting	Description / Comment Compact Fl13 Watt	Each	Qty 2 2	Estimated Unit Cost			Actual Unit Cost	

Report Run On: 4/2/2012

Measure 5 Smoke Detector is Needed			Components					Inspected		
C	Comment									
			Estimated			Actual				
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total	
1	Labor	Labor	Each	1						
1	Health and Safety	Smoke detector	Each	1						
(Other Detail						1			
				Measur	e Sub Total:] ;	Sub Total:		
	Field Notes:									
Į		г								
			Work Or	der Gra	nd Total:		Gran	d Total:		